

Office of the Chief Fire Officer
Karnataka Fire & Emergency Services
Pandoshwar Fire Station
Telecom House Road, Mangalore 575 001
Telephone: 2444045 (O) 2216082 (R)
Dated 18-10-2021

No.216/FSR/CFO/MD/2021

To,

✓ The Principal,
Shriniketana School,
Isloor,
Sirsi Talluk-581358,
Uttara Kannada Dist.

Sir,

Sub: Issue of 'compliance report' with respect to fire preventic
fighting and evacuation measures maintained : required
Shriniketana School, constructed at Sy.No.152/4, 152/2A Isloor
Village, Sirsi Taluk, Uttara Kannada District.

- Ref: 1) This office Advice Certificate No. 216/FSR/CFO/MD/2021
dated 15-07-2021.
2) Your letter dated 24-09-2021.

* * * * *

With reference to subject above cited, 'Fire Safety Recommendation' was issued wide
reference (1) to the premises of Shriniketana School, constructed at Sy.No.152/4, 152/2A, Isloor
Village, Sirsi Talluk, Uttara Kannada District with a condition to fulfill the recommendations and
compliance the same within 3 months.

With reference cited (2) above, the management of Shriniketana School had requested for the
compliance certificate from our department. In this regard the District Fire Officer, Uttara Kannada,
Karwar Fire Station was re-inspected on 10-10-2021 and submitted the report to issue Compliance
Certificate.

Under the above circumstances the Karnataka Fire & Emergency Services Department is
issuing the 'Fire Safety Compliance Certificate' to Shriniketana School, subject to proper
maintenance of fire fighting installations in good working conditions and to arrange the training of
40% of employees within 3 months and to renew the fire safety Recommendation report for every
year.

Note:- This Certificate is not consider as a Fire Safety Recommendation Report.



Yours faithfully,
[Signature] 13/10/21
Chief Fire Officer
Karnataka State Fire & Emergency Services
Mangalore

Copy to:

- 1) The Director, C.B.S.E., Shikshakendra 2, Community Centre, Preeth Vihar, Delhi-110092.
- 2) District Fire Officer, Uttara Kannada, Karwar.